MOTOROLA SOLUTIONS

CANCELLATION NOTICE

DGP 8000e/5000e UHF/VHF PORTABLE

Motorola Solutions is announcing the cancellation of the following MOTOTRBO DGP 8000e/5000e UHF/VHF Portable Radios.

PRODUCTS AFFECTED

RADIO	MODEL	DESCRIPTION
DGP 5050e	LAH56JDC9SA1AN	VHF (136-174MHz) NKP
	LAH56RDC9SA1AN	UHF (403-512MHz) NKP
DGP 8050e	LAH56JDC9RA1AN	VHF (136-174MHz) NKP
	LAH56RDC9RA1AN	UHF (403-512MHz) NKP
DGP 5550e	LAH56JDN9SA1AN	VHF (136-174MHz) FKP
	LAH56RDN9SA1AN	UHF (403-512MHz) FKP
DGP 8550e	LAH56JDN9RA1AN	VHF (136-174MHz) FKP
	LAH56RDN9RA1AN	UHF (403-512MHz) FKP

CRITICAL DATES

Last Order Date*	**March 31, 2023**

*Orders may not have a dispatch request date after July 31, 2023.

SUGGESTED PRODUCT REPLACEMENTS

Replacement models with similar features, functionalities and options but with additional new hardware and software features and enhancements are available and listed below.

RADIO	MODEL	DESCRIPTION
R7	LAH06JDC9WA2AN	VHF (136-174MHz) NKP Capable
	LAH06JDC9WA1AN	VHF (136-174MHz) NKP TIA Capable
	LAH06JDC9RA2AN	VHF (136-174MHz) NKP Enabled
	LAH06JDC9RA1AN	VHF (136-174MHz) NKP TIA Enabled
	LAH06RDC9WA2AN	UHF (403-527MHz) NKP Capable
	LAH06RDC9WA1AN	UHF (403-527MHz) NKP TIA Capable
	LAH06RDC9RA2AN	UHF (403-527MHz) NKP Enabled
	LAH06RDC9RA1AN	UHF (403-527MHz) NKP TIA Enabled
	LAH06JDN9WA2AN	VHF (136-174MHz) FKP Capable
	LAH06JDN9WA1AN	VHF (136-174MHz) FKP TIA Capable
	LAH06JDN9RA2AN	VHF (136-174MHz) FKP Enabled
	LAH06JDN9RA1AN	VHF (136-174MHz) FKP TIA Enabled
	LAH06RDN9WA2AN	UHF (403-527MHz) FKP Capable
	LAH06RDN9WA1AN	UHF (403-527MHz) FKP TIA Capable
	LAH06RDN9RA2AN	UHF (403-527MHz) FKP Enabled
	LAH06RDN9RA1AN	UHF (403-527MHz) FKP TIA Enabled

SERVICE AND SUPPORT

Only devices that are under an active service agreement or within a valid warranty period will continue to be supported for the duration of their outstanding service contract. No further service contract renewals will be available unless otherwise stated in writing by Motorola Solutions.

Following product cancellation, Motorola Solutions will make commercially reasonable efforts to support software critical bug fixes and hardware maintenance for a maximum

duration of 5 years. This duration is not guaranteed and may change at no notice depending on demand and related component availability or whether, due to component compatibility, legacy products are unable to support latest software releases.

Following the 5-year period of commercially reasonable effort, software maintenance and technical support will no longer be available and repair will be limited to the availability of spare parts held within the Repair Center. No further effort will be made to source parts outside of the Motorola Solutions Repair Centers

FOR MORE INFORMATION

For questions regarding the cancellation of the MOTOTRBO DGP 8000e/5000e, please contact your Motorola Solutions Account Representative.

Motorola Solutions values your privacy. See our Privacy Policy and Terms of Use. You can manage your communication preferences or unsubscribe at any time. You may also write to Motorola Solutions, Inc., Attention: Privacy Compliance Program, P.O. Box 59263, Schaumburg, IL USA 60159-0263 or email privacy1@motorolasolutions.com.

MOTOROLA, MOTO, MOTOROLA SOLUTIONS and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. © 2022 Motorola Solutions, Inc. All rights reserved.